Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

Operator: PEOPLES GAS LIGHT AND COKE CO.	Operator ID#: 15329
Inspection Date(s): 5/5/2015, 5/6/2015, 5/7/2015, 5/8/2015	Man Days: 4
Inspection Unit: North Shop	
Location of Audit: Chicago	
Exit Meeting Contact: Derek Leggitt	
Inspection Type: Design Testing and Construction	
Pipeline Safety Representative(s): Aaron McElravy	
Company Representative to Receive Report: Amy Kenny, Tom Webb	
Company Representative's Email Address: ALKenny@peoplesgasdelivery.com, TJWebb	@peoplesgasdelivery.com

CONSTRUCTION INFORMATION			
Location of Construction:		Construction P	erformed By:
4800 Block between Byron and Dakir	, Chicago IL	Michels Corpora	ation (PGL Contractor)
Contractor Foreman:	Paul Newholm		
Operator Inspector:	Donald Kirk (EN E	Donald Kirk (EN Engineering)	
	Person	(s) On Job Site	
Larry Mclauglin	Ма	rk Lebaron	Mike Anderson
Laverane Bates	Feri	nando Liles	Steve Bianchetta
Chris Hamilton			

# **Description of Construction:**

The construction project included the installation of 12 inch PE by open cut method, butt fusion of pipe and backfill. They were installing the pipe across the intersection of Dakin in the alley south of Cicero.

MAIN INSTALLATION		Status
[192.55]	Steel	No
[192.59]	PE	Yes
[192.59]	Other	No
[192.5]	Class location :	Class 4
[192.619,192.621,192.623]	MAOP	25psig
[192.63]	Pipe Size :	12 inch
[192.55,192.59]	Specification :	2406 / 2708

PEOPLES GAS LIGHT AND COKE CO./5-8-2015

Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

[192.55,192.59]	Manufacturer :	DriscoPlex 6500
[192.55,192.59]	Pipe Grade :	D2513
[192.55,192.59]	Wall Thickness :	DR13.5
[192.63(a)(2)]	Are pipe, valves, and fittings properly marked for identification?	Satisfactory
General Comment:		
All fittings and pipe observed contained the required ma	rkings.	
[192.227]	Date of Welder qualification:	Not Applicable
General Comment:		
The construction activities observed did not contain weld	ding of steel pipe.	
[192.227]	Welder's Name:	Not Applicable
General Comment:		
The construction activities observed did not contain weld	ding of steel pipe.	
[192.225,192.275,192.277,192.279,192.283]	Is pipe joined in accordance with approved written procedures?	Satisfactory
[192.285]	Date of Plastic Joining Qualification :	5-27-14
[192.285]	Joiner's name:	Steve Bianchetta
[192.455]	Is buried metallic pipe coated?	Not Applicable
General Comment:		
The audit included the installation of PE pipe, no steel p	ipe or fittings were observed during this inspection.	
[192.461]	Does coating meet 192.461?	Not Applicable
General Comment:		
The audit included the installation of PE pipe, no steel p	ipe or fittings were observed during this inspection.	
[192.455(a)(1)]	Is cathodic protection being provided?	Not Applicable
General Comment:		
The audit included the installation of PE pipe, no steel p	ipe or fittings were observed during this inspection.	
[192.455(a)(1)]	Is cathodic protection being provided? By Anodes:	Not Applicable
General Comment:		
The audit included the installation of PE pipe, no steel p	ipe or fittings were observed during this inspection.	
[192.455(a)(1)]	Is cathodic protection being provided? By Rectifier:	Not Applicable
General Comment:		
The audit included the installation of PE pipe, no steel p	ipe or fittings were observed during this inspection.	
[192.461(c)]	Is coating inspected just prior to being installed in the ditch?	Not Applicable

Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

General Comment:		
The audit included the installation of PE	Epipe, no steel pipe or fittings were observed during this inspection.	
[192.467]	Are pipelines electrically isolated from other underground metallic structures?	Not Applicable
General Comment:		
The audit included the installation of PE	Epipe, no steel pipe or fittings were observed during this inspection.	
[192.479]	Are above ground facilities cleaned and coated or jacketed as needed?	Not Applicable
General Comment:		
No above ground facilities were observ	ed during this inspection.	
[192.303]	Are comprehensive written construction specifications available and adhered to?	Satisfactory
[192.305]	Are inspections performed by the operator to check adherence to the construction specifications?	Satisfactory
[192.307]	Is material being visually inspected at the site of installation to ensure against damage that could impair its serviceability?	Satisfactory
[192.319]	Is ditch back-filled to provide firm support and prevent damage to pipe or coating?	Satisfactory
[192.321(c)]	Is plastic pipe installed as to minimize shear and tensile forces?	Satisfactory
[192.321(e)]	Does plastic pipe have means of locating while underground?	Satisfactory
[192.325]	Are required clearances from underground structures being maintained?	Satisfactory
[192.327]	Is required cover being obtained appropriate to type of pipeline and location?	Satisfactory
[192.503]	Are general testing requirements being met?	Not Applicable
General Comment:		
Staff did not observe testing of the main	n during the inspection.	
[192.517]	Are records being made of strength and leak tests?	Not Applicable
General Comment:	· · · · · · · · · · · · · · · · · · ·	
Staff did not observe testing of the main	n during the inspection.	
[192.807]	Were covered employees Operator Qualification records reviewed to ensure qualification?	Satisfactory
[192.805(c)]	Were non-qualified personnel being directed and observed by a qualified individual?	Satisfactory
[192.805(c)]	Were span of control limitations being followed?	Satisfactory
Was a Protocol 9 (Form 15) Co	mpleted?	No

Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

[192.614]	Were One Call Notifications performed as required?	Satisfactory
[192.614]	Dig Ticket #	560512684 559723222
[192.751]	Are adequate steps taken to minimize the potential for accidental ignition?	Satisfactory
[192.719(b)]	Was each repair made by welding to a transmission line made in accordance with 192.713, 192.715, and 192.717 and examined in accordance with 192.241?	Not Applicable

Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.